Owner Name and Address: Bureau of Indian Affairs 316 N 26th St Ste 4008 Billings MT 59101 Phone: (406) 657-6675

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0204022	Busby School of the Northern Cheyenne	US Highway 212	Busby	59016	(406) 592-3646	

TankID/Alt TankID Status	Tag Installed Number Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
5 / S5 Currently In Use	1/1/1998 08 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	ABC • E F • H 1 J & L B D E F • H 1 J & L	Yes Yes Yes Yes
6 / S6 Currently In Use	1/1/1998 08 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	B DEF . H 1 J K L	Yes Yes Yes Yes
7 / S7 Currently In Use	1/1/1998 08 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	B DEF H J J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 32

Owner Name and Address: Teepee Service Inc PO Box 245 Crow Agency MT 59022 Phone: (406) 638-2269

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0207334	Teepee Service Inc	Exit 509 Interstate 90	Crow Agency	59022	(406) 638-7277

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
7 / 07 Currently in Use	2097 7	7/3/1995 10 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF.HIJKL B DEF.HIJKL	Yes Yes Yes Yes
8 / 08 Currently in Use	2098 7		Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCDEFOHIJKL B (DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 32

Owner Name and Address: Sumack Trust DBA Little Bighorn Camp PO Box 266 Crow Agency MT 59022 Phone: (406) 638-2232

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0208937	Little Big Horn Camp	Interstate 90 & US Highway 212	Crow Agency	59022	(406) 638-2232

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
3 / 03 Currently In Use	3919	1/1/1999 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF®H1JKL B DEFGH1®KL	Yes Yes Yes Yes
4 / 04 Currently In Use	3920	1/1/1999 07 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.J.K.L B.DEF.G.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 32

Owner Name and Address: Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0210867	Battlefield Country Store	US Highway 212 & Interstate 90	Crow Agency	59022	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
5 / 05 Currently In Use	4174	2/1/2000 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKU B DEFOHIJKU	Yes Yes Yes Yes
6 / 06 Currently In Use	4175	2/1/2000 06 / No	Gasoline 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)J&U B (DEFOH)J&U	Yes Yes Yes Yes
7 / 07 Currently In Use	4176	2/1/2000 06 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)J&U B (DEFOH)J&U	Yes Yes Yes Yes
8 / 08 Currently In Use	4177	2/1/2000 06 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH))(C) (B (DEFOH))(C)	Yes Yes Yes Yes
9 / 09 Currently In Use	4178	2/1/2000 06 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJK) B (DEFOHIJK)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 32

Owner Name and Address: Indian Health Service 2900 4th Ave N Billings MT 59101 Phone: (406) 247-7171

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0213159	Crow Northern Cheyenne Hospital	Interstate 90 & US Highway 212	Crow Agency	59022	(406) 638-3499

TankID/Alt TankID Status	Tag Installe Number Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently in Use	4179 6/18/1993 13 /	Diesel No 10,149	STI-P3 Double-Walled	Bare Steel Double-Walled/Non-Corro	Safe Suction	● 0 E E G H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 32

Owner Name and Address: Chad & Brenda Fenner 203 N Terry Ave PO Box 7668 Yellowtail MT 59035 Phone: (406) 666-2333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0205862	Yellowtail Market	Parkdale Court	Fort Smith	59035	(406) 666-2333

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / 03 Currently In Use	1210	3/1/1998 08 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A • • D E F G H 1 J K L) • • E F G H 1 J K L	No Yes Yes Yes
4 / 04 Currently In Use	1211	3/1/1998 08 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A • • D E F G H) J K L • • E F G H) J K L	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 32

Owner Name and Address: National Park Service 5th Ave B PO Box 7458 Yellowtail MT 59035 Phone: (406) 666-3311

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0209815	Bighorn Canyon Maintenance Facility	5th Ave B	 Fort Smith	59035	(406) 666-2412

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
2 / 06 Currently in Use	1746	1/1/1988 18 / No	Diesel 2,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
3 / 05 Currently in Use	1745	1/1/1988 18 / No	Gasoline 2,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 32

Owner Name and Address: National Park Service 5th Ave B PO Box 7458 Yellowtail MT 59035 Phone: (406) 666-3311

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613877	OK A BEH Marina	5th Ave B	Fort Smith	59035	

TankID/Alt TankID Status	Tag Installe Number Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 07 Currently in Use	1747 5/14/1990	Gasoline No 2,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABC • EF • H 1) (K L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Chris Kortlander PO Box 200 Garryowen MT 59031 Phone: (406) 638-2012

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0203284	Garryowen Conoco	Garryowen Frontage Road	Garryowen	59031	(406) 638-2020

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Currently in Use	3392	6/21/1996 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Secondary Containment	Pressurized	8 0 E F G 8 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3393	6/21/1996 10 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Secondary Containment	Pressurized	ABCOEFOHIJKL B OEFGOIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 32

Owner Name and Address: Susan Greer 818 W 3rd Hardin MT 59034 Phone: (406) 665-1424

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0200061	Dollies Grocery	818 3rd St W	 Hardin	59034	(406) 665-1424

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently in Use	4463	12/20/1984 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A) B (C) E (F) G (H) (J) (K) L	Yes Yes Yes Yes
3 / 03 Currently in Use	4773	12/16/2002 03 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 10 of 32

Owner Name and Address: WY MT Investment Company PO Box 2468 Cody WY 82414 Phone: (307) 527-7575

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0200538	Hardin Texaco	1600 N Crawford Ave	Hardin	59034	(406) 665-2920

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 04 Currently in Use	3790	4/12/1974 32 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	ABC • E F G H 1 J K L B • E F G H 1 J K L	Yes Yes Yes Yes
3 / 03 Currently in Use	3789	4/12/1974 32 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHJJ%L B ●EFGHJJ%L	Yes Yes Yes Yes
5 / 05 Currently in Use	3791	4/12/1974 32 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	8 • EFGHJJKL	Yes Yes Yes Yes
6 / 06 Currently in Use	3792	4/12/1974 32 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC ● EFGH1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 32

Owner Name and Address: Graham Staunton Inc 16 W 3rd St PO Box 924 Hardin MT 59034 Phone: (406) 665-1611

Sys Fac I Location Name Location Street Address Location City Zip Location Phone

0201311 Graham Staunton Inc 16 W 3rd 16 3rd St W Hardin 59034

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / Currently in Use	0	/ No					B DEFGHIJKL	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 32

Owner Name and Address: Farmers Union Association 225 W Railroad PO Box 385 Hardin MT 59034 Phone: (406) 665-1103

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	1
0201403	Farmers Union Association	225 W Railroad St	 Hardin	59034	(406) 665-1103	_

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / S6 Currently in Use	923 6	6/1/1990 16 / Yes	Diesel 6,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
3 / S7 Currently in Use	924 6	6/1/1990 16 / Yes	Diesel 6,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (O) (E) (B) (H) (J) (K) (L)	Yes Yes Yes Yes
4 / S8 Currently in Use	925	6/1/1990 16 / Yes	Gasoline 6,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
5 / S9 Currently in Use	926 6	5/1/1990 16 / Yes	Gasoline 6,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 32

Owner Name and Address: Northern Cheyenne Tribal Schools PO Box 150 Busby MT 59016 Phone: (406) 477-3646

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0201769	Northern Cheyenne Tribal Schools Fire St	US Highway 212	Hardin	59034	(406) 477-3646	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
9 / S9 Currently In Use	507	12/1/1998 07 / No	Heating Oil 2,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	8 0 E F @ H 1 J K L	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 14 of 32

Owner Name and Address: Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0204841	Wagner Travel Shoppe Express Stop	1424 N Crawford Ave	Hardin	59034	(406) 665-1061

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
4 / 07 Currently in Use	2231	1/1/1990 16 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
5 / 08 Currently in Use	2232	1/1/1990 16 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (K) (D) EFGH() (K)	Yes Yes Yes Yes
6 / 09 Currently in Use	2233	1/1/1990 16 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (O) (E) (F) (H) (J) (V)	Yes Yes Yes Yes
7 / S4 Currently in Use	2234	4/3/1979 27 / Yes	Gasoline 14,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGH)J.L (B) (B) (B) (B) (B) (B) (B) (B) (B) (B)	Yes Yes Yes Yes
8 / S5 Currently in Use	2235	4/3/1979 27 / Yes	Gasoline 14,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGH)	Yes Yes Yes Yes
9 / S6 Currently in Use	2236	4/3/1979 27 / Yes	Diesel 14,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGH)J&L (BEFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 32

Owner Name and Address: Hanser Holding LLC 430 S Billings Blvd Billings MT 59101 Phone: (406) 248-7795

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0205561	Fox Service Center UST	25 3rd St E	Hardin	59034	(406) 665-3648

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
10 / S10	0 1/1/1965	Other	Asphalt Coated or Bare Steel	Other	Not Listed	ABCDEFGHIJKO	Yes
Currently In Use	41 / No	40	None	None		B DEFGHIJKO	No No No
11 / S11	0 1/1/1965	Other	Asphalt Coated or Bare Steel	Other	Not Listed	ABCDEFGHIJKO	Yes
Currently In Use	41 / No	40	None	None		B DEFGHIJKO	No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 16 of 32

Owner Name and Address: Alsaker Corp DBA Broadway Truck Stops PO Box 14646 Spokane WA 99214 Phone: (509) 534-150

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	l
0205752	Bairs Truck Stop Hardin	315 13th St W	Hardin	59034	(406) 665-1237	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently in Use	3894	4/25/1969 37 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(A	Yes Yes Yes Yes
3 / 03 Currently In Use	3895	4/26/1979 27 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
4 / 04 Currently in Use	3896	4/25/1969 37 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • • D E F G H J K L</pre> • • E F G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 32

Owner Name and Address: Gary & Lynette Vandersloot PO Box 156 Hardin MT 59034 Phone: (406) 665-3414

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0205856	L & B Last Stop	531 E Railroad St	Hardin	59034	(406) 665-3414

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / 03 Currently In Use	3915	1/1/1999 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	ABCDEF•H1J&L B DEFGH1•&L	Yes Yes Yes Yes
4 / 04 Currently In Use	3916	1/1/1999 07 / No	Gasoline 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	(A B C D E F • H 1 J K L B D E F G H 1 • K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 32

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0208703	Town Pump Inc Hardin	1012 N Crawford Ave	Hardin	59034	(406) 665-2423

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently in Use	2377	10/1/1984 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	2378	10/1/1984 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	2379	10/1/1984 21 / No	Diesel 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	2380	4/14/1981 25 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHUJKL • • EFGHUJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	2381	1/1/1977 29 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
6 / 06 Currently In Use	4362	5/1/2000 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 0 E F 0 H 1 J K L B 0 E F 0 H 1 J K L	Yes Yes Yes Yes
7 / 07 Currently In Use	4363	5/1/2000 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 0 E F 0 H 1 J K L B 0 E F 0 H 1 J K L	Yes Yes Yes Yes
8 / 08 Currently In Use	4364	5/1/2000 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 32

Owner Name and Address: Big Horn County Health Dept 809 N Custer Ave Hardin MT 59034 Phone: (406) 665-8720

Sys Fac ILocation NameLocation Street AddressLocation CityZipLocation Phone0210287Big Horn County Community Service Faci809 N Custer AveHardin59034(406) 665-1005

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
2 / 02	443 11/1/1998	Diesel	Polyethylene Tank Jacket	Flexible Plastic	Safe Suction	B DEFGHIJKL	Yes
Currently In Use	07 / No	2,000	Double-Walled	Double-Walled		B DEFGHIJKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 32

Owner Name and Address: Matovich Oil Co Inc PO Box 431 Hardin MT 59034 Phone: (406) 665-1400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0213423	Matovich Oil Co Inc	900 4th St W	Hardin	59034	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 03 Currently in Use	1582	5/24/1994 12 / No	Gasoline 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	B	Yes Yes Yes Yes
2 / 04 Currently in Use	1583	5/24/1994 12 / No	Diesel 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABC●EFGH)JKU B ●EFGH)JKU	Yes Yes Yes Yes
3 / 01 Currently in Use	1580	5/24/1994 12 / No	Gasoline 2,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
4 / 02 Currently in Use	1581	5/24/1994 12 / No	Diesel 2,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 32

Owner Name and Address: Farmers Union Association 225 W Railroad PO Box 385 Hardin MT 59034 Phone: (406) 665-1103

Sys Fac I	Location Name	Location Street Address		ocation City	Zip	Location Phone	
0213635	Farmers Union C Store	1223 N Crawford Ave	F	Hardin	59034	(406) 665-1155	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Currently in Use	927	7/1/1995 11 / No	Gasoline 16,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	928	7/1/1995 11 / No	Gasoline 16,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B D E F G H 1 J K L	Yes Yes Yes Yes
3 / 03 Currently in Use	929	7/1/1995 11 / No	Gasoline 16,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
4 / 04 Currently in Use	930	7/1/1995 11 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	931	7/1/1995 11 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 32

Owner Name and Address: Dominic Stevens Jr HC Box 150 Lodge Grass MT 59050 Phone: (406) 639-2684

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0206750	The Station Lodge Grass	250 Main St	Lodge Grass	59050	

TankID/Alt TankID Tag Status Numb	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Temporarily Out of Use	5/6/1979 27 / No	Gasoline 2,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No
2 / 02 Temporarily Out of Use	5/6/1979 27 / No	Gasoline 1,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJK● B DEFGHIJK●	No No No No
3 / 03 Temporarily Out of Use	5/5/1982 24 / No	Gasoline 2,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGH10K0 B DEFGH10K0	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 23 of 32

Owner Name and Address: Our Lady of Loretto Church PO Box 509 Lodge Grass MT 59050 Phone: (406) 639-2254

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0209970	Our Lady of Loretto Church	Harding Ave & Helen St	Lodge Grass	59050	(406) 639-2254	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / S2 Currently in Use	1778	7/23/1990 15 / No	Heating Oil 3,000	STI-P3 None	Copper Cathodically Protected	U.S. Suction	● DEFGHUJK L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 24 of 32

Owner Name and Address: Farmers Union Oil Co Lodge Grass Highway 87 PO Box 560 Lodge Grass MT 59050 Phone: (406) 638-2505

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
0209976	Farmers Union Oil Co Lodge Grass	Old US Highway 87	 Lodge Grass	59050	(406) 639-2413	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
9 / 09 Currently In Use	3603	12/1/1998 07 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • • D E F G H I J K L • • E F G H I J K L</pre>	Yes Yes Yes Yes
10 / 10 Currently In Use	3604	12/1/1998 07 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A • • D E F G H () () () ()	Yes Yes Yes Yes
11 / 11 Currently In Use	3605	12/1/1998 07 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	© © E E © H () J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 25 of 32

Owner Name and Address: William A Hoffman PO Box 130 Pryor MT 59066 Phone: (406) 252-9240

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0210164	Pryor Self Service	401 Mak Pua Ave	Lodge Grass	59050	(406) 252-9240

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / 03 Currently In Use	1389	10/1/1998 07 / No	Gasoline 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic None	Safe Suction	8 DEFGH10KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 26 of 32

Owner Name and Address: Lodge Grass School Dist 27 Drawer AF Lodge Grass MT 59050 Phone: (406) 639-2304

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0210772	Lodge Grass School Dist 27	124 N George St	Lodge Grass	59050	(406) 639-2304

TankID/Alt TankID Status		talled Prod		Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / 02 Currently In Use	4361 4/4/19	985 Diese / No 8,000	S .	Flexible Plastic Double-Walled	Safe Suction	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 27 of 32

Owner Name and Address: Plenty Coups High School 1 High School Ln PO Box 229 Pryor MT 59066 Phone: (406) 259-7329

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	1
0201131	Plenty Coups High School	1 High School Ln	Pryor	59066	(406) 259-7329	_

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
5 / 05 Currently In Use	1824 6	6/1/1998 08 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	A • C • E F G H I J K L B D E F G H I • K L	Yes Yes Yes Yes
6 / 06 Currently In Use	1825 6	6/1/1998 08 / No	Diesel 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	A • C • E F G H J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 28 of 32

Owner Name and Address: St Labre Indian School Education 1000 Tongue River Road Ashland MT 59003 Phone: (406) 666-2215

Association

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604505	Saint Charles Mission		Pryor	59066	(406) 784-2746

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / 02 Currently in Use	1958 8/20/1990 15 / No	Gasoline 1,000	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	ABC • E F G H J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 29 of 32

Owner Name and Address: St Labre Indian School Education 1000 Tongue River Road Ashland MT 59003 Phone: (406) 666-2215

Association

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0204504	Pretty Eagle School		Saint Xavier	59075	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / 03 Currently in Use	1956	4/1/1990 16 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	U.S. Suction	ABCOEFGHIJKL • DEFGHIJKL	Yes Yes Yes Yes
4 / S4 Currently in Use	3672	4/1/1990 16 / No	Heating Oil 10,000	STI-P3 None	Flexible Plastic Double-Walled	U.S. Suction	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 30 of 32

Owner Name and Address: Non Notified Unclaimed 2209 Phoenix Ave PO Box 200901 Helena MT 59620 Phone: () -

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0206446	Hi Way Service	Frontage Road off Interstate 90	Wyola	59089	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / S1 Currently in Use	,	4/9/1989 17 / Yes	Gasoline 1,100	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGH1J&L B DEFGH1J&	No Yes Yes No
2 / S2 Currently in Use		4/9/1989 17 / Yes	Gasoline 1,100	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEF6H1J&L B DEF6H1J&	No Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
		- J			
B Tank/Line Tightness Testing	ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 31 of 32

Owner Name and Address: Wyola School Dist No 29 PO Box 66 Wyola MT 59089 Phone: (406) 343-2722

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0213762	Wyola Elementary School	1 Mondale Ave	Wyola	59089	(406) 343-2722

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
2 / 02 Currently In Use	4370 7	7/1/1999 07 / No	Gasoline 1,000	STI-P3 Excavation Liner	Galvanized Steel Double-Walled/Non-Corro	Safe Suction	B DEFGHIOKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 32 of 32